Nº 10415

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-5-94	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 600	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 7F.5	
11.	NAME OF CONTRACTOR Jeffues Eye.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	Jan class out
230 CleAnout	
SIGNED Bill Panava	450 ZHSPECTION WH C'L' DEEDLY FILED AT ENGINEER'S OFFICE
/ /Inspector for City	/ LING NI ENGINEERO GIVIONEZZANIA

SA,

Nº 10415 7112

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, 200
RECEIVED OF	())))////// FEE OF \$/(6)
FOR WHICH PERMISSION IS GRANTED	<u> </u>
то тар	SEWER ON THE
OF 174 NUSE	AVE. ST. TYPE OF STREET
THE PREMISES BEING LOT NO	56C , HOUSE NO. 600
WORK TO BE DONE IN ACCORDANCE WITH CO	Section 29 odified Ordinances DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	1.5. Chemical &

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.