## Nº 10419

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-2-94	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	$\Lambda$ and $\Lambda$
WAS ATTACHED TO MAIN 7 5	NAME OF CONTRACTOR U. L. Luck
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	→10'V" - 17-17-1
	7'6 DESP
SIGNED BILL PORDAS	8'OFFP  FILED AT ENGINEER'S OFFICE
/ Inspector for City	· ·
DEMARKO	

14)

## Nº 10419

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u>ut 24</u>
RECEIVED OF	Jucob Collist	
OR WHICH PERMISSION IS GRANTED	1 111,700 0	
	SEWER ON THE	
Madriett Wit		
HE PREMISES BEING LOT NO. 150	The first of the first of the second of the	
ORK TO BE DONE IN ACCORDANCE WITH CONTRACTOR		202)
AME OF CONTRACTOR	JAMAN	- / Comet

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.