

Nº 10421

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-2-94

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 148'

HOUSE NO. 360

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR A. J. Cinson Const

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. J. Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

repair
N^o 10421

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, *Oct 28,*

RECEIVED OF *A.T. Connor*

FEE OF \$ *2⁰⁰*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *repair*

SEWER ON THE

OF *Virginia Ave SE*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *6947 & 6948*

HOUSE NO. *360*

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR *A.T. Connor*

*West Hanning
1 unit*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**