Nº 10422

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1805		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 455		
WAS ATTACHED TO MAIN 455	NAME OF CONTRACTOR Bet Ede	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
27° 4' 2'2'4" 8° 0' 6' 6' 6' 6' 6' 6' 6' 6' 6' 6' 6' 6' 6'	5'DEEP II'	
SIGNED Bill CAR	filed at engineer's office	
REMARKS		

Nº 10422

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	·
TO TAPSE	WER ON THE
OF GOLYAN St. DE ST. TY	
THE PREMISES BEING LOT NO.	, HOUSE NO
Section WORK TO BE DONE IN ACCORDANCE WITH (Codified Or OF THE DEPARTMENT OF PUBLIC SERVICE.	DULY PASSED BY THE CITY COUNCIL, AND dinances
NAME OF CONTRACTOR PLANE BOOTHER	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.