

N^o 10436

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-19-95

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES INTO MH

HOUSE NO. 2475

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Bill Lylich

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS CLEAN OUT IN BACK YARD AT END OF LINE.

Nº 10436 *tap*

OFFICE OF THE DIRECTOR OF PUBLIC SE

PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 17*

RECEIVED OF

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *10436*

TO TAP *San*

SEWER ON THE *S*

OF *W. Main Ave West*

AVE
ST TYPE OF STREET

THE PREMISES BEING LOT NO. *14912*

HOUSE NO. *2475*

WORK TO BE DONE IN ACCORDANCE WITH
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR *Glick Exc*

Don Tucci
1 unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**