Nº 10444

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1049	
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? IES	
WAS ATTACHED TO MAIN 1/55	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
7/3	1 7'8" DEEP 5'4" Pipe
73:11 6 Ann	"DEEP" FILED AT ENGINEER'S OFFICE
SIGNED / Inspector for City	THE AT ENGINEER OF THE PARTY OF
DEMARKS	·

Nº 10444/10

OFFICE OF THE DIRECTOR OF PUBLIC SE

	MASSIL	MASSILLON, OHIO,			
RECEIVED OF	Jack L	6,40	FE	E OF \$5C	
FOR WHICH PERMISSION IS GRANTED	<u> </u>	<u> </u>	· - -	·	
то тар	SEWER ON	THE	110		
of 14/ J/10 (69)	AVE. ST. TYPE OF S	TREET	***		
THE PREMISES BEING LOT NO	5003	, HOUSE NO.		49	
WORK TO BE DONE IN ACCORDANCE WIT OF THE DEPARTMENT OF PUBLIC SERVICE				1 1/25	
NAME OF CONTRACTOR	LICA		1 un	+	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.