## Nº 10446 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-1-95	IF SO HOW AND LOCATION FROM 59
HOUSE NO. 2597	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB? 455	
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR Malaute Ext
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	→7' <sub>17</sub>
	10,11 6 DEEP
$\frac{1}{2} \left( \frac{1}{2} \left( \frac{1}{2} \right) + \frac{1}{2} \left( \frac{1}{2} \right) \right) = \frac{1}{2} \left( \frac{1}{2} \left( \frac{1}{2} \right) + \frac{1}{2} \left( \frac{1}{2} \right) \right)$	220
	39/ 10'05 6/
SIGNED BILL Papara Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

## Nº 10446

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, 17, 1995
RECEIVED OF RICHARD MUPHY FEE OF \$5C
massillon, ohio, MM 17, 1995  RECEIVED OF RICHARD MUPHY FEE OF \$5C  FOR WHICH PERMISSION IS GRANTED.
TO TAPSEWER ON THE
of Fallen Oak lie n Eve. Type of STREET
THE PREMISES BEING LOT NO. 14853 , HOUSE NO. 2597
work to be done in accordance with Section 29 duly passed by the city council, and of the department of public service. Codified Ordinances
NAME OF CONTRACTOR PROPERTY EXC / Writ

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.