Nº 10460 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/25/95	IF SO HOW AND LOCATION FROM 84 / FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6" PLASTIC	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN_\(\sqrt{0} \sqrt{5} \)	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	5 220
では、 1000年 第8日まで	84' 220
SIGNED. ALC COM	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	,

Nº 10460

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLO	ON, OHIO, ////	4-19-
RECEIVED OF	Duch.	2 (Which	FEE OF \$50
OR WHICH PERMISSION IS GRANTED			·
O TAP	SEWER ON TH	HE	<u> </u>
FALLY SESIL			
HE PREMISES BEING LOT NO. 149			
VORK TO BE DONE IN ACCORDANCE WITH (Section 29 odified Ordinance	DULY PASSED BY THE	HE CITY COUNCIL, AND KOM CONST
IAME OF CONTRACTOR 444 274 C	14.t	/	(spec)

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.