## Nº 10464 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 7/1/95   | IF SO HOW AND LOCATION FROM OUT   |
|---|---|
| HOUSE NO. 2575  |   |
| SIZE OF PIPE USED   | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? 405  |   |
| WAS ATTACHED TO MAIN 405  | NAME OF CONTRACTOR MALAYITE   |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL  | L OF BUILDING SERVED.   |
| N Sel   | 10  |
| A PAREN   | 37  |
| **************************************  | 194'  |
| <i>6</i>  |   |
| <u> </u>  | TRILLIUM  |
| $\sim \sim $ | ••  |
| SIGNED 111 UU   | FILED AT ENGINEER'S OFFICE  |
| Inspector for City  |   |
| REMARKS   |   |

TAD

Nº 10464

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| MASSILLON, OHIO, 1200   |
|---|
| RECEIVED OF RECEIVED OF STEE OF \$TE  |
| DR WHICH PERMISSION IS GRANTED  |
| TAPSEWER ON THE   |
| AVE. TYPE OF STREET   |
| HE PREMISES BEING LOT NO. 14554 , HOUSE NO. 25.75                                 |
| ORK TO BE DONE IN ACCORDANCE WITH Section 29 DULY PASSED BY THE CITY COUNCIL, AND |
| AME OF CONTRACTOR JULIA LA                    |
| $f_{G}(x,y) = f_{G}(x,y)$   |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.