


Nº 10478

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED ? IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 59
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR HADERBANN
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

repair
Nº 10478

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 23*, 19*28*

RECEIVED OF *Holdebar* FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *water*

TO TAP *20" main sewer* SEWER ON THE *left* SIDE

OF *Paul Ave SE* AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *3885*, HOUSE NO. *59*

WORK TO BE DONE IN ACCORDANCE WITH *Section 29*
OF THE DEPARTMENT OF PUBLIC SERVICE. *Codified Ordinances* DULY PASSED BY THE CITY COUNCIL, AND RULES

NAME OF CONTRACTOR *Holdebar*

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.