Nº 10481 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8/11/95 HOUSE NO. 1150	IF SO HOW AND LOCATION FROM 154	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? (CS		
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	8' 45' v 22 V 22' O	
SIGNED Inspector for City	151' Cue FILED AT ENGINEER'S OFFICE	

10481

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

and the second of the second o	ASSILLON, OHIO,
RECEIVED OF	## FEE OF \$50
FOR WHICH PERMISSION IS GRANTED	<u></u>
TO TAPSEWER	
DE ST. TYPE	
THE PREMISES BEING LOT NO. 14920	and the second s
WORK TO BE DONE IN ACCORDANCE WITH Section 2	Duly passed by the city council, and nances Min Lily 6
NAME OF CONTRACTOR)))/TC/LC/LC/	
	•

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.