

N<sup>o</sup> 10498

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-17-95

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

64'

HOUSE NO. 2105

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

B. H. Leach

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas  
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10498

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO

Nov 14

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Glick exl

TO TAP

San

SEWER ON THE

west

OF

CYPRUS

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

15067

HOUSE NO.

2105

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Glick exl

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**