Nº 10504

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-141-95	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM GOES INTO MANHOLE DOWN STREAM
HOUSE NO <i>999</i>	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 755	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A.J. Diania
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	B 2'DEEP
e e e e e e e e e e e e e e e e e e e	Clean Open Bidg. 220 Los Inspection FILED AT ENGINEER'S OFFICE.
SIGNED Bill Pappas	22° INS PECTION THE FILED AT ENGINEER'S OFFICE.
/ inspector for City	

Nº 10504

tap of Sandew are Sul OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	<u> </u>	<u> </u>
RECEIVED OF	<u>L)(# 117-</u>	1/6/12	FEE OF \$/
FOR WHICH PERMISSION IS GRANTED	<u> </u>		
TO TAPSEV			the state of the s
of July School St. Ty	PE OF STREET		
THE PREMISES BEING LOT NO. 1 2 141/6	, Hou <u>ş</u>	E NO,	<u> 199 — </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO			
NAME OF CONTRACTOR AJ Wanson)W	KU/ 	unit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.