

N^o 10512

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-29-96

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

132'

HOUSE NO. 806

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

J. Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

6' deep 60' - 30° 8' 6" DEEP
5' 8 1/4"



N
7

SIGNED Bill Rogers

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

tap
N^o 10512

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb 28*

RECEIVED OF

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**