Nº 10546

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 3-7-96 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---|---|
| HOUSE NO3 5// | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? 125 | Suit of contractor Eslich Was daine |
| WAS ATTACHED TO MAIN 45 | NAME OF CONTRACTOR Estech Wreckause |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | |
| 0 120 | TO N |
| SIGNED BELO COMMISSIONED Inspector for City | FILED AT ENGINEER'S OFFICE |
| REMARKS | |

Nº 10546

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TER SEWER

| MASSILLON, OHIO, DATE |
|---|
| RECEIVED OF CALCA WILLOWA FEE OF \$ 5 |
| FOR WHICH PERMISSION IS GRANTED. |
| TO FART - OF ALLISTALLY SEWER ON THE |
| of State NW AVE. STATE NW AVE. ST. TYPE OF STREET |
| THE PREMISES BEING LOT NO. 341 |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND |
| NAME OF CONTRACTOR ALLIANS AND |
| |
| Note: This permit covers work outside of building only. Any work |

walls of building is subject to Massillon Board of Health Regulations.