
Nº 10561

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-4-96	IF SO HOW AND LOCATION FROM
	FIRST MANHOLE DEWAND STREAM
HOUSE NO	4/2
. "	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?_ NES	
7/	NAME OF CONTRACTOR Malante Eye
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.
	
•	12' + 1'per/
	177/
: 	5-4"
	13' 0
>	J- 45°-22
`	127'450 4' 9'6" DEF/3
	1 43 B11 1 DEF/2
SIGNED BELL COORS	1 96 DP./
SIGNED 7 Inspector for City	FILED AT ENGINEER'S OFFICE
/ // inspector for only	
· · · · · · · · · · · · · · · · · · ·	

Nº 10561

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER



Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.