

Nº 10562

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-27-96

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 404

SIZE OF PIPE USED

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Budaya Wrecking



Nf

↑

CURB

SIGNED

Ric Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

CUT-OFF

OFFICE OF THE DIRECTOR OF PUBLIC SE

Nº 10562

PERMIT TO ~~TAP~~ ^{CAP} SEWER

MASSILLON, OHIO,

Aug 22

RECEIVED OF

H + W Contractors

FEE OF \$1⁰⁰

FOR WHICH PERMISSION IS GRANTED

none

TO TAP

Cut-off sanitary

SEWER ON THE

North

OF

Oak Ave SE

AVE.

ST. TYPE OF STREET

Residential

THE PREMISES BEING LOT NO.

9189

, HOUSE NO.

406

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

St. Mary's Church

NAME OF CONTRACTOR

H + W Contractor's

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**