N° 10576

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED_3-11-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN: STREAM 140	
HOUSE NO. 2650		
SIZE OF PIPE USED_6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No		
WAS ATTACHED TO MAIN YUES	NAME OF CONTRACTOR Molaritie Exc	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
4.5° 9'DE	56 6. 0 14'DEEP NA	
SIGNED Bir Copyright Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	84899	

Nº 10576

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, ACAT
RECEIVED OF MADS SUCCEPTION FEE OF \$ C
FOR WHICH PERMISSION IS GRANTED
TO TAP AAT SEWER ON THE YLCITA
OF MI (A A A A A SEWER ON THE YEAR OF THE OF STREET ACCO.)
THE PREMISES BEING LOT NO. 11980, HOUSE NO. 3650
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR MALLELLE M. Maries

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.