Nº 10598

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-12-96	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 245-5		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN 2 3	NAME OF CONTRACTOR On The Section of Contractor	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
125' 12'DEED		
SIGNED 33 Junispector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	·	

## Nº 10598

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF The Company of the August	-1 Assa FEE OF \$
FOR WHICH PERMISSION IS GRANTED 120101	<u>COMPTING</u>
то тар <u></u>	VER ON THE
OF	PE OF STREET ZZZZZZZZZZZZ
THE PREMISES BEING LOT NO.	, HOUSE NO. 2455
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	5. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
NAME OF CONTRACTOR JANA S CAPAVAT	NG UNIT

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.