

Nº 10606

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-15-97

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

117'

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Dechard Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pason

Inspector for City

INSPECTION NH

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10606

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

1/3

RECEIVED OF _____

FEE OF _____

400

FOR WHICH PERMISSION IS GRANTED _____

TO TAP _____

SEWER ON THE _____

OF _____

AVE.

ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. _____

, HOUSE NO. _____

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**