## Nº 10611

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-10-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DEPART STREAM 100			
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH			
WAS LATERAL AT CURB? 75	NAME OF CONTRACTOR Malmiter Ever			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	920-301 50 4"			
SIGNED Bill Chippector for City	TILED AT ENGINEER'S OFFICE			

## Nº 10611

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO,		42
RECEIVED OF	LE frysk i inde	1.17	FEE OF \$==2.1
FOR WHICH PERMISSION IS GRANTED			
TO TAPSeeSE	WER ON THE	addit.	
OF AVE. T	YPE OF STREET	oxixida.	
THE PREMISES BEING LOT NO.	Hous,,	SE NO. LAL	70
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.	10. 19-1971 DULY F	ASSED BY THE C	ITY COUNCIL, AND
NAME OF CONTRACTOR 70 10 10 10 10 10 10 10 10 10 10 10 10 10	Coplandent	t.	

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.