Nº 10614

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALE	NAME OF CONTRACTORL. OF BUILDING SERVED.

SIGNED	Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	No Inspection	did Not call	
	,		

Cutoff

The second of th
VENTURE DESCRIPTION OF PUBLIC SERVICE
PERMIT TO TAP SEWER TOLL FREE OND UTILITIES PROTECTION SERVICE
OHIO UTILITIES PROTECTION SERVICE NON-MERIBERS MUST BE CALLED DIRECTLY MASSILLON. OHIO. 2/24 19 97
RECEIVED OF Eslich Weeking FEE OF \$ 15:00
${\it y}$
OR WHICH PERMISSION IS GRANTED
TO JAP CUT OF SEWER ON THE SOUTH SIDE OF LIEUTANT SEWER ON THE STATES THE PREMISES BEING LOT NO. 9352 HOUSE NO. 625
of Lewart Sur ST. TYPE OF STREET asphalt
THE PREMISES BEING LOT NO. 9352 HOUSE NO. 625
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES
OF THE DEPARTMENT OF PUBLIC SERVICE.
$\prime\prime$

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

NAME OF CONTRACTOR CALLED WILCKING