Nº 10619

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-17-9.7	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
House No. 304			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN 455	NAME OF CONTRACTOR Cathell Wiesking		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
Z	15th 41 22 22 22 22 22 22 22 22 22 22 22 22 22		
SIGNED BULL POSAUL (Inspector for City	FILED AT ENGINEER'S OFFICEy		
REMARKS			

Nº 10619

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER Cu

	MASSILLON, OH	0,3/1-7
RECEIVED OF	- Alan Colla	FEE OF \$ 15
FOR WHICH PERMISSION IS GRANTED		
Cuta-1/6-	SEWER ON THE	
of At	AVE.	Heridelt.
THE PREMISES BEING LOT NO.	<i>ी ्रां</i> , , нс	DUSE NO. 304
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE.	ORDINANCE NO. 19-1971 DULY	
NAME OF CONTRACTOR	t AtCALA	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.