## $N^{0}$ 10638

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5/6-97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM GGES JALO MAL
HOUSE NO. 433	
SIZE OF PIPE USED 4/1-2"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	· Section of the sect
<i>Ų</i>	4. J 24.
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	90 ( 31/ Brings Paris)  90 ( 31/ Brings Paris)
SIGNED Bill Papous	FILED AT ENGINEER'S OFFICE
Inspector for City	
	. The world the second of the

## Nº 10638

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/5  RECEIVED OF LIGHT TOTAL FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED
TO TAP SEWER ON THE LULY
THE PREMISES BEING LOT NO. 01/09 32 A , HOUSE NO. 433
THE PREMISES BEING LOT NO. 01/09.32 A , HOUSE NO. 433
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.