## $N^{0}$ 10648

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 678.97	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO. 266					
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB? 7 5					
17	NAME OF CONTRACTOR 26 ADa language				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
	→25' 17 X/A				
	9' -450				
	20 450				
	20' 450 4' - 5'DEFD				
SIGNED BUILD	FILED AT ENGINEER'S OFFICE				
Inspector for City					
DEMARKS					

## Nº 10648

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON	I, OHIO,	6/11	_
RECEIVED OF		entrus	FEE OF \$5	أم
FOR WHICH PERMISSION IS GRANTED	<i>U</i>			
TO TAP JULY JULY OF 1/1 LA JULY SE	SEWER ON THE		·	<u>.</u> –
OF 11th SI JE	AVE. ST. TYPE OF STREE	т	andret	
THE PREMISES BEING LOT NO				
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE		DULY PASSED BY	THE CITY COUNCIL, AND	)
NAME OF CONTRACTOR 741-840	rbourns	,		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.