Nº 10696

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16-26-98 IF SO HOW AND LOCATION FROM 0 5 7 NO 2011
HOUSE NO57@
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE OWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? No
WAS ATTACHED TO MAIN 45 5 NAME OF CONTRACTOR WELDER
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
LA NA
22 19
SIGNED SECO COMPANY FILED AT ENGINEER'S OFFICE
Inspector for City

Nº 10696

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

// MASSILLON, OHIO,/_/3
RECEIVED OF July Holder Braund FEE OF \$57
OR WHICH PERMISSION IS GRANTED
O TAP SEWER ON THE ALLTA
FARMALL TE ST. TYPE OF STREET CASPAGE
THE PREMISES BEING LOT NO. 13907 , HOUSE NO. 510
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR AND ALL COLUMN

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.