Nº 10711

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-21-98	IF SO HOW AND LOCATION FROM 4/5/	
HOUSE NO. 233/		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	\mathcal{L}_{i}	
WAS ATTACHED TO MAIN 75	NAME OF CONTRACTOR BILL Alice	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
LA X	32	
<u>'</u>	7'5'7568	
SIGNED BILL Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 10711

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

·	MASSILLON,	оню,3//
RECEIVED OF	Bell Warn	4 FEE ORS DE
OR WHICH PERMISSION IS GRANTED	A A TOTAL CONTRACTOR OF THE PARTY OF THE PAR	
O TAP	SEWER ON THE	and the same
or the strong list		
THE PREMISES BEING LOT NO.		/
		DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR		
Note: This permit	covers work outside o	of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.