

Nº 10712

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-27-98

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

GOES INTO MH

HOUSE NO. 223

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Kaldenbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill P. P...
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10712

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/24

RECEIVED OF Hilbermann

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED

TO TAP repair

SEWER ON THE west

OF 5th St NE

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 582

HOUSE NO. 223

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hilbermann

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**