

Nº 10732

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-1-98

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 213'

HOUSE NO. 1407

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR H & W Eng.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Birdo Capas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 10732

OFFICE OF THE DIRECTOR OF PUBLIC SEI

PERMIT TO TAP SEWER

MASSILLON, OHIO, 664

RECEIVED OF Hou

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE South

OF West 100th

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO.

HOUSE NO. 1407

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hou

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**