Nº 10739

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-9-98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 500	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO SET Y	
WAS ATTACHED TO MAIN 75 9	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BOILDING SERVED,
e de la companya de	SET 1 - 450 9'DEEP
	48'
	5'PE 90 15.
	G-EASE
- 0	Trap
SIGNED BUT Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 10739

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSIL	LON, OHIO,	7/8
RECEIVED OF A CLUSSE	•	FEE OF \$202
FOR WHICH PERMISSION IS GRANTED		
TO TAPSEWER ON		
OF HEALTH ALL SE ST. TYPE OF ST	TREET JOJÁN	l.t
THE PREMISES BEING LOT NO. 0 (1001	, HOUSE NO	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-19 OF THE DEPARTMENT OF PUBLIC SERVICE.	371 DULY PASSED BY THE CITY	COUNCIL, AND
NAME OF CONTRACTOR A CLARA		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.