

Nº 10746

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-11-98

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

6'

HOUSE NO.

1003

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

MICABLE Plumbing

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Purpus

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Top of pipe missing, Replaced 3' of pipe

Nº 10746

Repair
OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sep 10*

RECEIVED OF

Michael Flaming
FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

TO TAP

Repair
SEWER ON THE *4143rd*

OF

AVE.

4143rd
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

9150

, HOUSE NO.

1013

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

S. J. J.

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**