Nº 10749

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-23.98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM S S S S S S S S S S S S S
HOUSE NO. 26.50	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	10°
WAS ATTACHED TO MAIN 725	NAME OF CONTRACTOR JOHN COLD
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	3'4 5'6" DEEP 22°10' DEEP
SIGNED B CO Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 10749

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	·	ILLON. OHIO.	9/2	3
RECEIVED OF				FEE OF \$
·	The state of	-/	<u> </u>	
FOR WHICH PERMISSION IS GRANTED	X-423-2	Carly Line		
TO TAP	SEWER ON	A THE	2-1	
10 IAC	CENTEN OF			
OF CAPLULA SE	AVE. ST. TYPE OF S	STREET	anih	<u> </u>
<i>— (1</i>			ž	
THE PREMISES BEING LOT NO	15024	, House !	vo2/_	<u> 50</u>
WORK TO BE DONE IN ACCORDANCE WITH	ORDINANCE NO. 19-1	971 DULY PAS	SED BY THE CITY	COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE				
NAME OF CONTRACTOR	a Stau	at 10		
	/	A	#:1	A
Note: This permit cov	ers work outs	lae of bull	aing oniy.	Any work

walls of building is subject to Massillon Board of Health Regulations.