Nº 10752

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-4-98	IF SO HOW AND LOCATION FROM 75/	
HOUSE NO. 7/7		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	(+1-08 (c) C	
WAS ATTACHED TO MAIN 75 5	NAME OF CONTRACTOR COMMENT	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	6'DEED	
+ + + + + + + + + + + + + + + + + + +	CURB mt	
SIGNED BUILD Conspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 10752

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	9/29	
RECEIVED OF		FEE OF \$ 🗐 🕹 .	
FOR WHICH PERMISSION IS GRANTED	<u>L</u>		
TO TAP A MARIE SE	EWER ON THE	and former of	
OF AVE. TO	YPE OF STREET	in A. L. Sortina	
THE PREMISES BEING LOT NO	· · · · · · · · · · · · · · · · · · ·		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	e e e e e e e e e e e e e e e e e e e		
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.