Nº 10783

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO					
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?					
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR				
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.				
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE				
Inspector for City					
REMARKS					

Nº 10783

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHION OV 24					
RECEIVED OF	Frank	Burko	: 1 +		FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	with.	- Ligari	tolog l	LACZ	vall. oc	
TOJAPCUT SZANTOWY	SEWER C	N THE	Nact	<u>i </u>	 -	
OF Oberling An SW	AVE. ST. TYPE OF	STREET	Asph	ait	··	
THE PREMISES BEING LOT NO.	Z <u>&</u> S	, Hous	SE NO	920		
WORK TO BE DONE IN ACCORDANCE WITH ORI OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19	-1971 DULY F	PASSED BY	THE CITY	COUNCIL, AND	
NAME OF CONTRACTOR Burkett	Exaz	vating.				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.