Nº 10796

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED /2-/7-98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2375	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 15	
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR Malerille Exp
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.
SIGNED BULL	15' 8'sq'' 5' 22° 10'0889
SIGNED 8 10 Inspector for City	FILED AT ENGINEER'S OFFICE
mapector for only	
DEMANUS	

Nº 10796

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•	MASSILLON, OHIO,	12/16
RECEIVED OF A PURCHE	<u></u>	FEE OF \$5Z
FOR WHICH PERMISSION IS GRANTED		
TO TAPSE	EWER ON THE	£
OF HULLAUTE DE SE. T	YPE OF STREET Q-Q-y-	lalt_
THE PREMISES BEING LOT NO. 172/	/, HOUSE NO	25
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NOT THE DEPARTMENT OF PUBLIC SERVICE.	NO. 19-1971 DULY PASSED BY THE CIT	Y COUNCIL, AND
NAME OF CONTRACTOR) Allauite		

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.