Nº 10824

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-30-9 9 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | | |
|------------------------------|---|--|--|
| HOUSE NO. 2380 | | | |
| SIZE OF PIPE USED 6 1/ | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | | |
| | CURB LINE AND DEPTH | | |
| WAS LATERAL AT CURB? 75 E | | | |
| WAS ATTACHED TO MAIN 14 6 | NAME OF CONTRACTOR Malaritie Colice. | | |
| · . | | | |
| | LL OF BUILDING SERVED. | | |
| signed Bill Carrier for City | FILED AT ENGINEER'S OFFICE | | |

Nº 10824

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| a | | 3/7 |
|--|------------------|-------------|
| RECEIVED OF JURGEN | MASSILLON, OHIO, | FEE OF \$ 5 |
| | \mathcal{O} | · |
| OR WHICH PERMISSION IS GRANTED | | |
| OTAR Statutating SEL | VER ON THE | -12-t |
| - Unwersely Dy SEAVE TY | PE OF STREET | eplant |
| o TAP SAMUALLY SEVENTE ST. TY X aview ST 15/15 HE PREMISES BEING LOT NO. 15/15 | , HOUSE NO | 2350 |
| ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO | | |
| F THE DEPARTMENT OF PUBLIC SERVICE. | | |
| IAME OF CONTRACTOR Muliute | | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.