

N^o 10833

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-16-99

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2485

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pearson
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Sewer had to be raised up 2"

Nº 10833

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 25

RECEIVED OF Homes By John Harshbarger FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Bontrager Excavating

TO TAP Sanitary SEWER ON THE West

OF Augusta Dr. SE AVE. ST. TYPE OF STREET Concrete

THE PREMISES BEING LOT NO. 15480, HOUSE NO. 2485

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Bontrager Excavating

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.