Nº 10857

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM				
HOUSE NO. 2455					
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB? 155	A				
WAS ATTACHED TO MAIN 7/3 C	NAME OF CONTRACTOR Malitation Edge				
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
	6 2892 10'84				
SIGNED Bill Carper	FILED AT ENGINEER'S OFFICE				
/ inspector for City					
DEMARKS	·				

Nº 10857

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON	, OHIO,	June	<u></u>
RECEIVED OF	<u> Astrogushed</u>	1-10011	.	. FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED	islatando Ex	cauchm	<u> </u>	
то тар	•	-	' .	
or				
THE PREMISES BEING LOT NO				
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SER		DULY PASSED	BY THE CITY	COUNCIL, AND
NAME OF CONTRACTOR $\mathcal{L}(A)$	ute Executing			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.