Nº 10873

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	20-99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1/85	·	
SIZE OF PIPE USED	. 7	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	109	. The state of th
WAS ATTACHED TO MAIN		NAME OF CONTRACTOR BONTAGE SAC
the state of the s	and the second s	ALL OF BUILDING SERVED.
e v	1 °,	8'4 731 450
	. # ⁷ * - \$.	[3]
No. 1	e e e e e e e e e e e e e e e e e e e	24'450
		18' 10' DEEP
SIGNED	Bee (V)	FILED AT ENGINEER'S OFFICE
OIGHED	Inspector for Cit	
nettable		$1 + s_{1} + s_{2} + s_{3} + s_{4} + $

Nº 10873

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

8,1997	RECEIVED OF FEE OF \$ 55
"cicat How	RECEIVED OF FEE OF \$ 55
Dr. 54	FOR WHICH PERMISSION IS GRANTED
2	TO TAPSEWER ON THE
	OF MAN E SE ST. TYPE OF STREET ASPA
: <i>5</i> *	THE PREMISES BEING LOT NO. 15625, HOUSE NO. 187
5	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
* cooper	NAME OF CONTRACTOR BEALT RAZLE
	Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.