Nº 10891

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8.2099 HOUSE NO. 306	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN 7/2 5	NAME OF CONTRACTOR BILDANIE Wreston	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	22'	
	0-252 36 page	
SIGNED Bill Paris	FILED AT ENGINEER'S OFFICE	
Inspector for City		
DEMARKO		

Nº 10891

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, /////L	15
RECEIVED OF	BUCKEYE WIECKING	FEE OF \$
	Buckeye Wirelking	
TOTAL CONTO	sewer on the East	
	AVE. ST. TYPE OF STREET ACHES!	
THE PREMISES BEING LOT NO. 49	, HOUSE NO	306
WORK TO BE DONE IN ACCORDANCE WITH OF THE DEPARTMENT OF PUBLIC SERVICE,	ORDINANCE NO. 19-1971 DULY PASSED BY T	HE CITY COUNCIL, AND
NAME OF CONTRACTOR BUCKEYE	wheeking	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.