Nº 10893

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-23-79 HOUSE NO. 2325	IF SO HOW AND LOCATION FROM CORS INTO MH	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 75 5	NAME OF CONTRACTOR Malarite Go.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	10 + 6 DET P	
e e e e e e e e e e e e e e e e e e e	2 220	
SIGNED Bile C	45 20 6 DEEP  FILED AT ENGINEER'S OFFICE	
Inspector for City		

## **№** 10893

## OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

D	MASSILLON, OHIO,	8//3
RECEIVED OF	Vaglan	FEE OF \$5L
FOR WHICH PERMISSION IS GRANTED	Doubte	
TO TAPSE	WER ON THE	<u>«</u>
OR ALL OF ST. TY	PE OF STREET AND A	lalt
THE PREMISES BEING LOT NO	, HOUSE NO	2321
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	O. 19-1971 DULY PASSED BY THE	E CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR	y or	·

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.