## $N^{0}$ 10931 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-25-99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 2205				
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	$\phi_{i}$ , $\phi_{i}$			
4./	NAME OF CONTRACTOR Malautus Egas			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	6684" + F. B. 20			
6 M	220			
	10 DEEPS			
SIGNED TO LE CONTRACTOR CITY	FILED AT ENGINEER'S OFFICE			
/ Inspector for City				

## Nº 10931

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

Mi DE

	MASSILLON,	OHIOLLTOSC	<u></u>
RECEIVED OF	ite Exc	- · ·	FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
TO TAP SCHITCH	SEWER ON THE	Noc 11 times !-	
OF UNIVERSITY DOSE AV	E. I. TYPE OF STREET		<del></del>
THE PREMISES BEING LOT NO. 15791		, HOUSE NO. 22(	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC OF THE DEPARTMENT OF PUBLIC SERVICE.	E NO. 19-1971 [	DULY PASSED BY THE	CITY COUNCIL, AND
NAME OF CONTRACTOR MALAYITE EX	c for	Hoors by A	shloy

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.