## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-25-59	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 2730 - 97-40		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN TES	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
15' 450 450 45' 450 45' 450 45' 450		
SIGNED BELL PROPERTY	FILED AT ENGINEER'S OFFICE	
REMARKS		

## Nº 10933

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•	,
7	MASSILLON, OHIO, /O/J6
RECEIVED OF	Equil FEE OF \$
OR WHICH PERMISSION IS GRANTED	
O TAP 11 12 12 12 SE	wer on the last
of Dundly Colored	•
HE PREMISES BEING LOT NO. VILLE	,
YORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	IO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.