

Nº 10946

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

00/00/00

Lateral to MH ?

DATE INSPECTED-----2245-----

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM-----

HOUSE NO.-----6"-----

SIZE OF PIPE USED-----yes-----

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH-----


WAS LATERAL AT CURB?-----yes-----

Malavit EXC.

WAS ATTACHED TO MAIN-----

NAME OF CONTRACTOR-----

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED-----

Inspector for City

FILED AT ENGINEER'S OFFICE-----

REMARKS-----

Nº 10946

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/10

RECEIVED OF Malanta Excavating

FEE OF \$50

FOR WHICH PERMISSION IS GRANTED

TO TAP Sanitary

SEWER ON THE West

OF Hammerly Dr. SE

AVE.
ST.

TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 15781

HOUSE NO. 2245

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Asdley Homes

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**