Nº 10948

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	335'	
HOUSE NO. 2125 SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
was lateral at cure? 6 was attached to main yes	NAME OF CONTRACTOR	Malavite Exc.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	LL OF BUILDING SERVED.	2125 University	
	1++	10'4'-	
		77/45'	
Θ		2325,	
SIGNED Jeffs in Jun Anspector for City	FILED AT EN	GINEER'S OFFICE	
· · · · · · · · · · · · · · · · · · ·			

Nº 10948

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,			,
RECEIVED OF	Distu	ryited Hines	FEE OF \$	51
FOR WHICH PERMISSION IS GRANTE	o Malaule.	<u> Excusating</u>		
TO TAP SAMPLALY	SEWE	R ON THE AOTA	um e la el	
OF JAINELSHY PLINE	AVE. TYPE	OF STREET ASPAN	H	
THE PREMISES BEING LOT NO	5804	House No.	2/25	
WORK TO BE DONE IN ACCORDANCE OF THE DEPARTMENT OF PUBLIC SE		19-1971 DULY PASSED	BY THE CITY COUNCIL, AI	ND R
NAME OF CONTRACTOR MAIL	astle		,	

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.