Nº 10957

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 63-99	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1170	·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	m 1 = 1 . 0 .
WAS ATTACHED TO MAIN 55	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
put -	99' - 22° 1' - 10' page
SIGNED BELO Tipspector for City	FILED AT ENGINEER'S OFFICE
r inspector for only	
REMARKS	

Nº 10957

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, NOV 24
RECEIVED OF MATAVITE EXCEVENTION FEE OF \$50
FOR WHICH PERMISSION IS GRANTED MELZYIFE EXCEVETING
•••
OF Wheelon Cir WE ST. TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. 15649 , HOUSE NO. 1170
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Malarite Excavaling
-

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.