Nº 10962

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 12-16= 99	IF SO HOW AND LOCATION FROM GOES 7/1/2 2021		
HOUSE NO. 3088			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 15 5			
WAS ATTACHED TO MAIN #2 5	NAME OF CONTRACTOR Haldoware		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	220 25' 20' 20' 20' 20' 20' 20' 20' 20' 20' 20		
SIGNED BUILD Conspector for City	filed at engineer's office		

Nº 10962

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

•	MASSILLON, OHIO,	December 16	
RECEIVED OF		FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	Hodelowa Plumb	103 + Duna	
то тар <i>\$a.udul</i> .y			
or			
THE PREMISES BEING LOT NO. 149		•	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Holder Kal	VM	·	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.