

N^o 10988

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/16/00

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 116'

HOUSE NO. 310


SIZE OF PIPE USED 6"
WAS LATERAL AT CURB? yes

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Tissot

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M. King
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 10988

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

03/07

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Test Excavating

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

15188

, HOUSE NO.

310

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Test

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**