

Nº 11009

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____ FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11009

Repair

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *3-6*

RECEIVED OF *Gay Hudson*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

TO TAP *San*

SEWER ON THE *St.*

OF *State*

AVE.

ST.

TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO. *9*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Gay Hudson*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**