Nº 11019

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED3-14-00	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1840		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? 78 5		
WAS ATTACHED TO MAIN 455 5	NAME OF CONTRACTOR Malautie Exa	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	5'squ'in 6' 8' DEEP 450 18'	
SIGNED Bill Pansas Anispectar for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 11019

OFFICE OF THE DIRECTOR OF PUBLIC SE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 3/15	
\mathcal{L}	,	
RECEIVED OF	Aguished Howes FEE OF \$5	
FOR WHICH PERMISSION IS GRANTED	Quite-	
TO TAP	sewer on the <u>last</u>	
OF LA CANDOL DY SE ST.	TYPE OF STREET UNFILLE	
THE PREMISES BEING LOT NO.	79 , HOUSE NO. 1860	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND		
OF THE DEPARTMENT OF PUBLIC SERVICE.	/	
NAME OF CONTRACTOR ALLEGALIZADA	1 Horaco	

Note: This permit covers work outside of building only. Any worl walls of building is subject to Massillon Board of Health Regulations.